Daily Work History (by Work Location) Period: 6/1/2013 - 6/30/2013

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

Precinct 1: County Roads		
Location	Date	Work Done
Creekview Dr /CW between HCR 1211 and HCR 1210	6/10/2013	Bladed surface; Added rock
Giant Cedar Dr between Giant Cedar Dr and HCR 1207	6/24/2013	Hauled materials for work crew hauled 1 load of base to Giant Cedar;12 loads of base to 1207
Perch Cir between Appaloosa St and Giant Cedar Dr	6/18/2013	Hauled materials for work crew hauled 1 load of road base to Perch Circle;1 load to Appolossa;3 loads to Giant Cedar
	6/18/2013	Hauled materials for work crew hauled 1 load of base to Perch Circle;1 load to Appalossa; 3 loads to Giant Cedar
Quarter Horse Rd	6/6/2013	Added road base material
	6/17/2013	Overlaid road with asphalt hauled 2 loads of road base to 1207; completed chip seal of Quarterhorse
	6/17/2013	Overlaid road with asphalt Cxompleted chip seal of Quarterhorse
HCR 1104 LP between HCR 1159 and HCR 1104 LP	6/27/2013	Hauled materials for work crew hauled 1 load of base to 1159;hauled 10 loads of base to 1104
HCR 1104 LP between HCR 1212 and HCR 1207	6/26/2013	Hauled materials for work crew hauled 1 load of base to 1104;2 loads to 1212;2 loads to 1207;1 load to 1228
HCR 1207	6/17/2013	Hauled materials for work crew hauled 1 load of base;completed chip seal of Quarterhorse
	6/17/2013	Bladed surface; Added rock completed chip seal of Quarterhorse
	6/24/2013	Hauled materials for work crew hauled 7 loads of base to 1207
HCR 1207 between HCR 1425 and HCR 1212	6/25/2013	Hauled materials for work crew hauled 2 loads to 1207;4 loads to 1425;1 load to 1212
HCR 1210	6/12/2013	Bladed surface; Added rock worked on distyributiobn truck; new batteries;swept quarterhorse
HCR 1210 between HCR 1102 and HCR 1207	6/13/2013	Hauled materials for work crew used backhoe to spread base on Hilltop and Crowsx foot;hauled 2 loads of base to 1210;1 load to 1211;1 load to 1207
HCR 1210 between HCR 1211 and Hilltop	6/13/2013	Hauled materials for work crew

Printed 7/3/2013 Page 1 of 2

Daily Work History (by Work Location)

Period: 6/1/2013 - 6/30/2013

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

Precinct 1: County Roads		
HCR 1211 between HCR 1210 and HCR 1211	6/13/2013	Bladed surface; Added rock bladed Four Feathers, Crowsfoot;1211;1210;added rock
HCR 1212 between HCR 1212 and HCR 1207	6/26/2013	Hauled materials for work crew hauled 3 loads of base to 1212; 2 loads to 1207
HCR 1227 between HCR 1210 and HCR 1211	6/12/2013	Hauled materials for work crew hauled 5 loafds of base to 12267;1 load to 1211;1 load to 1210
HCR 1227 between HCR 1211 and HCR 1210	6/12/2013	Hauled materials for work crew hauled 5 loads of base to 1227;1 load tyo 1211; 1 load of base to 1210
	6/12/2013	Bladed surface; Added dirt
HCR 1248 between HCR 1240 and HCR 1250	6/10/2013	Bladed surface; Added rock
HCR 1305	6/5/2013	Bladed surface; Added rock hauled gravel from 2604 to Country Club to prepare for seal coating
	6/5/2013	Hauled materials for work crew hauled 3 loads of base to 1305
HCR 1305 between HCR 1311 and HCR 1314	6/10/2013	Bladed surface; Added rock graded 1211; hauled 1 load of base to 1248
HCR 1311 between HCR 1306 and HCR 1311	6/11/2013	Hauled materials for work crew hauled 4 loads of base to 1311;1 load to 1306
HCR 1314 between HCR 1305 and HCR 1314	6/10/2013	Hauled materials for work crew hauled 6 losds of base to 1314 and 1 load to 1305.
HCR 1314 between HCR 1311 and HCR 1306	6/11/2013	Hauled materials for work crew Hauled 3 loads of base to 1314;1 load to 1311;1 load to 1306
HCR 1413 W between HCR 1418 and HCR 1425	6/25/2013	Bladed surface; Added rock bladed 1425 N and 1425 s
HCR 1414 between HCR 1414 and HCR 1405	6/24/2013	Bladed surface; Added rock
HCR 1414 between HCR 1414 and HCR 1413 W	6/20/2013	Trimmed brush or trees
HCR 1424 between HCR 1429 and HCR 1429	6/26/2013	Bladed surface; Added rock bladed 1104;1433, and 1434
HCR 1425 between HCR 1207 and HCR 1212	6/25/2013	Hauled materials for work crew hauled 3 loads of base to 1425;1 load to 1212;2 loads to 1207
HCR 1429 between HCR 1414 and HCR 1429	6/19/2013	Trimmed brush or trees

Printed 7/3/2013 Page 2 of 2