Daily Work History (by Work Location)

Period: 3/1/2012 - 3/31/2012

Work: All categories and types

All Assignments

Location: All locations in all areas

Hill County

Precinct 1: County Roads		
Location	Date	Work Done
Creekwood Dr /CW	3/23/2012	Bladed surface; Pulled shoulders or ditches
Hilltop between Crowfoot Ln and Circle Rd	3/29/2012	Bladed surface
Quail Lake E between Happy Ln and Pleasant Dr	3/28/2012	Bladed surface
HCR 1143	3/1/2012	Hauled materials for work crew hauled 1 load of base
	3/1/2012	Hauled materials for work crew hauled 5 loads of rock
HCR 1150	3/7/2012	Bladed surface; Added rock
HCR 1159	3/8/2012	Bladed surface; Added rock
	3/12/2012	Cleaned outfall ditch
	3/15/2012	Bladed surface; Added rock hauled 6 loads of over-sized rock to fill hole on 1159
HCR 1201	3/5/2012	Bladed surface; Added rock
HCR 1206	3/6/2012	Bladed surface; Added rock
HCR 1212	3/15/2012	Bladed surface; Added rock bladed 1212 from 3050 to FM 934
HCR 1217 between HCR 1217 and HCR 1221	3/15/2012	Hauled materials for work crew hauled 4 loads of over-sized rock to 1217;2 loads of base to 1221
HCR 1217 between HCR 1227 and HCR 1256	3/14/2012	Hauled materials for work crew
HCR 1228	3/26/2012	Bladed surface; Pulled shoulders or ditches
HCR 1230	3/20/2012	Bladed surface; Added rock
HCR 1231	3/19/2012	Bladed surface; Added rock
	3/22/2012	Hauled materials for work crew
HCR 1236	3/21/2012	Bladed surface; Added rock
	3/22/2012	Bladed surface; Added rock
HCR 1239	3/27/2012	Bladed surface; Pulled shoulders or ditches
HCR 1248 between Juniper Cove Rd and Timberline Dr	3/30/2012	Patched road surface

Printed 4/9/2012 Page 1 of 3

Daily Work History (by Work Location)

Period: 3/1/2012 - 3/31/2012

Work: All categories and types

Location: All locations in all areas

Hill County

HCR 1300 3/14/2012 Bladed surface; Added rock HCR 1303 3/7/2012 Bladed surface; Added rock HCR 1306 3/6/2012 Bladed surface; Added rock HCR 1306 3/6/2012 Bladed surface; Added rock 3/15/2012 Hauled materials for work crew hauled 4 loads of base 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/25/2012 Hauled materials for work crew hauled 5 loads of base 4 Robult/replaced bridge Yoder construction compnay installed a box culvent 3/8/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/9/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 4/12/2012 Bladed surface; Added rock 4/12/2012 Bladed surface; Added rock 4/12/2013 Bladed surface; Added rock	Precinct 1: County Roads		
HCR 1300 3/14/2012 Bladed surface; Added rock HCR 1303 3/7/2012 Bladed surface; Added rock HCR 1306 3/6/2012 Bladed surface; Added rock HCR 1306 3/15/2012 Bladed surface; Added rock 3/15/2012 Bladed surface; Added rock 3/19/2012 Hauled materials for work crew hauled 4 loads of base 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Rebuilt/replaced bridge Yoder construction compnay installed a box culvert 3/8/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/8/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 4/12/2012 Repaired bridge ap	HCR 1256	3/5/2012	Bladed surface; Added rock
HCR 1303 3/7/2012 Bladed surface; Added rock HCR 1306 3/6/2012 Bladed surface; Added rock 3/15/2012 Bladed surface; Added rock 3/19/2012 Hauled materials for work crew hauled 4 loads of base 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Rebuilt/replaced bridge Yoder construction compnay installed a box culvert 3/8/2012 Hauled materials for work crew hauled 1 load of over-sized rock 3/8/2012 Hauled materials for work crew hauled 1 load of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/13/2012	Hauled materials for work crew hauled 5 loads of flex-base
HCR 1306 3/6/2012 Bladed surface; Added rock 3/15/2012 Bladed surface; Added rock 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 4/8/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 4/8/2012 Hauled materials for work crew hauled 3 load of over-sized rock 3/8/2012 Hauled materials for work crew 4/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/9/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches HCR 1429 3/5/2012 Repaired bridge approaches HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 1440 loads of base 1	HCR 1300	3/14/2012	Bladed surface; Added rock
3/15/2012 Bladed surface; Added rock 3/19/2012 Hauled materials for work crew hauled 4 loads of base 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 3/8/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 3/8/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 4 Hauled materials for work crew hauled 5 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 load of over-sized rock 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base	HCR 1303	3/7/2012	Bladed surface; Added rock
Hauled materials for work crew hauled 4 loads of base 3/19/2012 Hauled materials for work crew hauled 2 loads of base	HCR 1306	3/6/2012	Bladed surface; Added rock
HCR 1361 3/19/2012 Hauled materials for work crew hauled 2 loads of base HCR 1364 3/29/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Rebuilt/replaced bridge Yoder construction compnay installed a box culvert 3/8/2012 Hauled materials for work crew hauled 10ad of over-sized rock 3/8/2012 Hauled materials for work crew hauled load of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/9/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 4/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 4/12/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Hauled materials for work crew hauled 5 loads of base 4/13/2012 Hauled materials for work crew hauled 5 loads of base 4/13/2012 Hauled materials for work crew hauled 5 loads of base		3/15/2012	Bladed surface; Added rock
HCR 1361 3/26/2012 Hauled materials for work crew hauled 3 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled 5 loads of base HCR 1364 3/5/2012 Hauled materials for work crew hauled load of over-sized rock and size of the		3/19/2012	Hauled materials for work crew hauled 4 loads of base
HCR 1364 3/5/2012 Rebuilt/replaced bridge Yoder construction compnay installed a box culvert 3/8/2012 Hauled materials for work crew hauled load of over-sized rock 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 4/12/2012 Repaired bridge approaches 4/13/2012 Repaired bridge approaches 4/13/2		3/19/2012	Hauled materials for work crew hauled 2 loads of base
HCR 1364 3/5/2012 Rebuilt/replaced bridge Yoder construction compnay installed a box culvert 3/8/2012 Hauled materials for work crew hauled load of over-sized rock 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 4/12/2012 Re	HCR 1361	3/26/2012	Hauled materials for work crew hauled 3 loads of base
culvert 3/8/2012 Hauled materials for work crew hauled load of over-sized rock 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 4/2/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches 4/2/2012 Repaired bridge approaches 3/13/2012 Bladed surface; Added rock 4/2/2012 Bladed surface; Added rock 4/2/2012 Hauled materials for work crew hauled 5 loads of base 4/2/2012 Bladed surface; Added rock 4/2/2012 Hauled materials for work crew hauled 5 loads of base		3/29/2012	Hauled materials for work crew hauled 5 loads of base
3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches 4/13/2012 Repaired bridge approaches 4/13/2012 Repaired bridge approaches 4/13/2012 Bladed surface; Added rock 4/14/2012 Bladed surface; Added rock 4/14/2013 Bladed surface; Added rock	HCR 1364	3/5/2012	· · · · · · · · · · · · · · · · · · ·
3/8/2012 Hauled materials for work crew 3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/8/2012	Hauled materials for work crew hauled load of over-sized rock
3/8/2012 Hauled materials for work crew hauled 2 loads of over-sized rock 3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches 4/CR 1429 3/5/2012 Bladed surface; Added rock 4/CR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock 4/CR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/8/2012	Hauled materials for work crew
3/9/2012 Rebuilt/replaced bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches 4CR 1429 3/5/2012 Bladed surface; Added rock 4CR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock 4CR 1446 between HCR 1159 and HCR 1446 3/13/2012 Hauled materials for work crew hauled 5 loads of base 4CR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/8/2012	Hauled materials for work crew
3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock 3/12/2012 Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches 4 Repaired bridge approaches 5 Repaired bridge approaches 6 Repaired bridge approaches 7 Repaired bridge approaches 7 Repaired bridge approaches 8 Repaired bridge approaches 9 Repaired bridge appr		3/8/2012	Hauled materials for work crew hauled 2 loads of over-sized rock
Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 4/6/2012 Hauled materials for work crew hauled 5 loads of base		3/9/2012	Rebuilt/replaced bridge
back fill new bridge 3/12/2012 Hauled materials for work crew hauled 3 loads of base 3/12/2012 Repaired bridge approaches Repaired bridge approaches 3/13/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S Hauled materials for work crew hauled 5 loads of base		3/12/2012	Hauled materials for work crew hauled 3 loads of over-sized rock
3/12/2012 Repaired bridge approaches 3/13/2012 Repaired bridge approaches Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/12/2012	Hauled materials for work crew hauled 3 loads of over-sized rock top back fill new bridge
3/13/2012 Repaired bridge approaches HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/12/2012	Hauled materials for work crew hauled 3 loads of base
HCR 1429 3/5/2012 Bladed surface; Added rock HCR 1446 between HCR 1159 and HCR 1446 3/13/2012 Bladed surface; Added rock HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base		3/12/2012	Repaired bridge approaches
HCR 1446 between HCR 1159 and HCR 1446 HCR 1450 S 3/13/2012 Bladed surface; Added rock Hauled materials for work crew hauled 5 loads of base		3/13/2012	Repaired bridge approaches
HCR 1450 S 3/6/2012 Hauled materials for work crew hauled 5 loads of base	HCR 1429	3/5/2012	Bladed surface; Added rock
	HCR 1446 between HCR 1159 and HCR 1446	3/13/2012	Bladed surface; Added rock
3/6/2012 Hauled materials for work crew hauled 2 loads of base and 2 over-siz	HCR 1450 S	3/6/2012	Hauled materials for work crew hauled 5 loads of base
		3/6/2012	Hauled materials for work crew hauled 2 loads of base and 2 over-size

Printed 4/9/2012

Daily Work History (by Work Location)

Period: 3/1/2012 - 3/31/2012

Work: All categories and types

Location: All locations in all areas

Hill County

Precinct 1: County Roads		
HCR 1450 S	3/6/2012	Hauled materials for work crew hauled 1 load of base
	3/6/2012	Hauled materials for work crew HULED 3 LOADS OF BASE AND 2 LOADS OF OVER-SIZED ROCK
	3/7/2012	Hauled materials for work crew hauled 4 loads of base
	3/7/2012	Hauled materials for work crew hauled 5 loads of base
	3/8/2012	Cleaned ditches
	3/9/2012	Replaced road culvert
	3/20/2012	Cleaned outfall ditch
	3/26/2012	Set road drainage culvert
HCR 1458	3/1/2012	Hauled materials for work crew hauled 1 load of base
	3/1/2012	Hauled materials for work crew hauled 1 load of base
	3/22/2012	Bladed surface; Added rock
County: Other Class: Other Type		
Location	Date	Work Done
(location not on list)	3/3/2012	Worked at precinct barn worked adult probation-4 workers
	3/26/2012	Traveld to Houston to take applicators test
	3/26/2012	Traveled to Houiston to take test for applicators liscense
	3/27/2012	Took applicators test in Houston
	3/27/2012	took applicators liscense test
	3/28/2012	completed applicators test;passed and returned to Blum
	3/28/2012	completeds applicatorsw test;passed and returned to Blum

Printed 4/9/2012 Page 3 of 3