Work: All categories and types

Location: All locations in all areas

Precinct 1: County Roads

All Assignments

| Location | Date | Work Done |
|--|-----------|---|
| Country Club Rd | 6/8/2016 | Patched road surface Picked up a load of gravel from Trinity for patch machine |
| | 6/8/2016 | Patched road surface |
| Country Club Rd between Country Club Rd and Juniper Cove Rd Patched potholes on Quarterhorse, | 6/8/2016 | Patched road surface pickeded up a load of gravel for patcher |
| Country Club Rd between Country Club Rd and Juniper Cove Rd Patched Timberline | 6/7/2016 | Patched around mailbox |
| County Barn | 6/2/2016 | Worked at precinct barn repaired brakes on # 11 trailer |
| | 6/2/2016 | Worked at precinct barn serviced county equipment |
| | 6/15/2016 | Worked at precinct barn repaired spray patcher; repaired chip spreader |
| Ezell Dr | 6/9/2016 | Set road drainage culvert |
| | 6/9/2016 | Set road drainage culvert |
| Fort Graham Rd N between Fort Graham Rd N and HCR 1137 Cleared brush and fallen trees from 1250,1240 & 1248 | 6/1/2016 | Cleared debris or fallen tree |
| Fort Graham Rd N between Fort Graham Rd N and HCR 1248 Cleared trees on 1250 and 1305 | 6/1/2016 | Cleared debris or fallen tree |
| Pinto Ridge between Pinto Ridge and Appaloosa St filled pot holes on Cross Street,Mohon | 6/6/2016 | Patched road surface |
| Pinto Ridge between Pinto Ridge and Appaloosa St repaired potholers on Mohon, used load of base on Pinto Ridge;over-sized rock on Appalossa;1/2 lload 0of base on Mobhon | 6/6/2016 | Patched road surface |
| Pinto Ridge between Pinto Ridge and Cross St patch road surface on A[ppalossa | 6/6/2016 | Patched road surface |
| Timberline Dr | 6/13/2016 | Patched road surface |
| | 6/14/2016 | Patched road surface |
| | 6/14/2016 | Patched road surface took Volvo to mechanic for repaires; filled patch machine with P2. |

Work: All categories and types

Location: All locations in all areas

All Assignments

Hill County

| Precinct 1: County Roads | | |
|---|-----------|---|
| Timberline Dr at/near Timberline Dr | 6/13/2016 | Patched road surface |
| Timberline Dr between Timberline Dr and Lone Star St Patched potholes on Bellmont | 6/14/2016 | Patched road surface |
| HCR 1106 | 6/13/2016 | Trimmed brush or trees |
| HCR 1130 S | 6/16/2016 | Set road drainage culvert |
| | 6/16/2016 | Set road drainage culvert set culvert carred truck to Lone Star for repairs |
| HCR 1145 LP | 6/14/2016 | Hauled materials for work crew hauled 8 loads of base to 1145 |
| | 6/14/2016 | Hauled materials for work crew hauled 8 loads of base to 1145 N. |
| | 6/14/2016 | Mowed grass shot grade to place culverts on 1439&1432 |
| | 6/14/2016 | Bladed surface; Added rock spread 16 loads of base obn 1145 |
| | 6/15/2016 | Hauled materials for work crew hauled 9 loads of base to 1145 |
| | 6/15/2016 | Hauled materials for work crew hauled 1 load of base to 1145 |
| | 6/15/2016 | Bladed surface; Added rock |
| | 6/16/2016 | Overlaid road with asphalt hauled 7 loads of base to 1145 North |
| | 6/16/2016 | Bladed surface; Pulled shoulders or ditches |
| | 6/20/2016 | Hauled materials for work crew |
| | 6/20/2016 | Hauled materials for work crew hauled $41/2$;loads of base to 1256 ; $1/2$ load of base to 1240 |
| HCR 1145 LP between HCR 1145 LP and HCR 1256 bladed 1240 | 6/20/2016 | Bladed surface; Added rock |
| HCR 1145 LP between HCR 1145 LP and HCR 1367 | 6/20/2016 | Hauled materials for work crew |
| | 6/20/2016 | Hauled materials for work crew hauled 1 load of base to 1145;3 loads of base to 1367;2 loads of base to 1414 N. |
| HCR 1145 LP between HCR 1145 LP and Juniper Cove Rd Mohon,2415 | 6/6/2016 | Patched road surface |
| HCR 1206 between HCR 1303 and HCR 1414 filled in sink holes on 1413 7 n1206 | 6/1/2016 | Patched road surface |

Work: All categories and types

Location: All locations in all areas

All Assignments

Hill County

| Precinct 1: County Roads | | |
|--|-----------|--|
| HCR 1211 between HCR 1211 and HCR 1195 shredded 1210 and 1211 | 6/29/2016 | Trimmed brush or trees |
| HCR 1212 | 6/13/2016 | Set road drainage culvert hauled 2 load of base/1 load of over-sized rock |
| | 6/13/2016 | Set road drainage culvert bladed in over-sized rock on 1206 |
| HCR 1212 between HCR 1212 and HCR 1145 LP shredded 11206 & 2415 | 6/6/2016 | Trimmed brush or trees |
| HCR 1212 between HCR 1212 and HCR 2415 HCR 1145, repaired roadway on 1145 | 6/6/2016 | Patched road surface |
| HCR 1221 between HCR 1221 and HCR 1207 cleared culverts on 1206,1221& 1207 | 6/2/2016 | Hauled materials for work crew hauled 1 loads of base to 1413;2 loades of base to 1413 |
| | 6/2/2016 | Hauled materials for work crew |
| HCR 1240 between HCR 1240 and HCR 1256 | 6/21/2016 | Hauled materials for work crew |
| | 6/21/2016 | Hauled materials for work crew hauled 1 load of base to 1256;4 loads of base to 1240 |
| HCR 1241 between HCR 1241 and Quarter Horse Rd | 6/22/2016 | Trimmed brush or trees |
| HCR 1248 between HCR 1240 and HCR 1248 | 6/28/2016 | Trimmed brush or trees |
| HCR 1256 | 6/21/2016 | Hauled materials for work crew hauled 1 load of base to HCR 1256 |
| | 6/22/2016 | Bladed surface; Added rock |
| HCR 1256 between HCR 1256 and HCR 1240 | 6/21/2016 | Bladed surface; Added rock |
| HCR 1303 | 6/27/2016 | Bladed surface; Added rock |
| | 6/28/2016 | Bladed surface; Added rock |
| | 6/28/2016 | Hauled materials for work crew hauled 6 loads of base to 1303 |
| HCR 1303 between HCR 1303 and HCR 1306 | 6/27/2016 | Hauled materials for work crew hauled 21 load of base to 1303;1 load to 1306 |
| HCR 1303 between HCR 1303 and HCR 1458 | 6/28/2016 | Hauled materials for work crew |
| | 6/28/2016 | Hauled materials for work crew hauled 1 load of base to 1303;5 loads of base to 1458 |

Work: All categories and types

Location: All locations in all areas

| Precinct 1: County Roads | | |
|--|-----------|--|
| HCR 1306 | 6/29/2016 | Bladed surface; Added rock |
| | 6/29/2016 | Hauled materials for work crew hauled 5 loads of base to 1306 |
| | 6/30/2016 | Hauled materials for work crew hauled 5 loads of base to 1306 |
| HCR 1306 between HCR 1306 and HCR 1303 | 6/27/2016 | Set road drainage culvert |
| HCR 1314 | 6/15/2016 | Cleared debris or fallen tree worked in the shop on chip spreader; repaired power washer |
| | 6/15/2016 | Cleared debris or fallen tree |
| HCR 1355 between HCR 1355 and HCR 1303 | 6/27/2016 | Hauled materials for work crew hauled 2 loads of base to 1355;2 loads to 1303 |
| | 6/27/2016 | Hauled materials for work crew hauled 2 loads of base to 1355;2 loads to 1303 |
| HCR 1355 between HCR 1355 and HCR 1458 | 6/27/2016 | Bladed surface; Added rock |
| HCR 1361 between HCR 1361 and HCR 1369 | 6/21/2016 | Bladed surface; Added rock |
| HCR 1361 between HCR 1361 and HCR 1369 Inspected roads for road damage following heavy rains | 6/13/2016 | Other road work |
| HCR 1367 | 6/20/2016 | Hauled materials for work crew |
| HCR 1367 between HCR 1367 and HCR 1364 Bladed 1363 | 6/20/2016 | Bladed surface; Pulled shoulders or ditches |
| HCR 1413 W | 6/8/2016 | Hauled materials for work crew |
| | 6/8/2016 | Hauled materials for work crew hauled 7 loads of base to 1413;2 loads of over-sized rock to 1413 |
| HCR 1413 W between HCR 1413 W and HCR 1414 bladed 1417 and 1414 North | 6/8/2016 | Bladed surface; Added rock |
| HCR 1413 W between HCR 1413 W and HCR 1414 Bladed 1418,1207,1221, 1206, 1159 | 6/2/2016 | Bladed surface; Added rock |
| HCR 1414 | 6/14/2016 | Hauled materials for work crew hauled 2 loads of base to 1414 |
| | 6/20/2016 | Bladed surface; Pulled shoulders or ditches |
| | 6/22/2016 | Hauled materials for work crew hauled 6 loads of base to 1414 N. |

Work: All categories and types

Location: All locations in all areas

All Assignments

Hill County

| Precinct 1: County Roads | | |
|---|-----------|---|
| HCR 1414 | 6/22/2016 | Bladed surface; Added rock |
| HCR 1414 between HCR 1414 and HCR 1240 | 6/22/2016 | Hauled materials for work crew hauled 1 load of base to 1414 N.;1 load of base to 1240;1 load of base to 1256;2 loads of base to 1414 N |
| | 6/22/2016 | Hauled materials for work crew |
| HCR 1414 between HCR 1414 and HCR 1361 hauled 3 loads of base to 1369 | 6/21/2016 | Hauled materials for work crew hauled 2 loads of base to 1414;1 load of base to 1361 |
| | 6/21/2016 | Hauled materials for work crew |
| | 6/21/2016 | Hauled materials for work crew hauled 2 loads of base to 1414 N.;1 load of of base to 1361 |
| | 6/21/2016 | Hauled materials for work crew |
| HCR 1414 between HCR 1414 and HCR 1413 W | 6/2/2016 | Hauled materials for work crew hauled 2 loads of over-sized rock to 1414;1 load of base to 1413 |
| | 6/2/2016 | Hauled materials for work crew |
| HCR 1414 between HCR 1414 and HCR 1425 | 6/22/2016 | Bladed surface; Added rock |
| HCR 1414 trepiared #11 belly dump trailer | 6/1/2016 | Patched road surface |
| HCR 1425 | 6/29/2016 | Bladed surface; Added rock |
| | 6/30/2016 | Bladed surface; Pulled shoulders or ditches |
| HCR 1425 between HCR 1425 and HCR 1221 bladed HCR 1413 | 6/30/2016 | Bladed surface; Added rock |
| HCR 1429 between HCR 1429 and HCR 1424 | 6/28/2016 | Bladed surface; Pulled shoulders or ditches |
| HCR 1430 | 6/9/2016 | Bladed surface; Pulled shoulders or ditches |
| HCR 1432 | 6/23/2016 | Set road drainage culvert |
| | 6/23/2016 | Set road drainage culvert hauled 1 load of base to cover culvert installation |
| | 6/23/2016 | Set road drainage culvert hauled 1 load of base to 1432 |
| | 6/23/2016 | Set road drainage culvert |
| HCR 1432 between HCR 1432 and HCR 1433 started grading but due to heavy rains had to quit | 6/2/2016 | Bladed surface; Added rock |

to heavy rains had to quit

Work: All categories and types

-

Location: All locations in all areas

| Precinct 1: County Roads | | |
|---|-----------|--|
| HCR 1433 between HCR 1433 and HCR 1413 W haul3ed gravel to 1434 | 6/8/2016 | Overlaid road with asphalt hauled3 loads of base to 1433 & 34 |
| HCR 1433 between HCR 1433 and HCR 1433 | 6/8/2016 | Bladed surface; Added rock pulled ditches on 1439 |
| HCR 1433 between HCR 1433 and HCR 1434 | 6/7/2016 | Hauled materials for work crew hauled patch machine to P2 for emulsion; hauled 4 loads of base to 1434 |
| | 6/7/2016 | Hauled materials for work crew |
| HCR 1434 | 6/7/2016 | Bladed surface; Pulled shoulders or ditches |
| | 6/7/2016 | Bladed surface; Pulled shoulders or ditches Inspected Chisholm Trail subdivision. Culverts needed repair |
| | 6/8/2016 | Overlaid road with asphalt hauled 3 loads of base to 1434 |
| HCR 1434 between HCR 1434 and HCR 1227 cleared culverts on 1227,1207;check road condition on 1206,1150 & 1201 | 6/2/2016 | Hauled materials for work crew hauled 2 loads of base on 1434 |
| HCR 1434 between HCR 1434 and HCR 1433 | 6/7/2016 | Hauled materials for work crew hauled 3 loads of base to 1434;1 load of base to 1433. |
| | 6/7/2016 | Hauled materials for work crew |
| HCR 1439 | 6/30/2016 | Set road drainage culvert |
| | 6/30/2016 | Hauled materials for work crew hauled 2 loads of rock to 1439 & 1432 |
| HCR 1444 between HCR 1444 and HCR 1446 shredded brush on 1221,1207 & 1206 | 6/2/2016 | Trimmed brush or trees |
| HCR 1450 S between HCR 1450 S and HCR 1369 | 6/22/2016 | Bladed surface; Pulled shoulders or ditches |
| HCR 1458 | 6/29/2016 | Bladed surface; Added rock |